DigiSign Verified: D2099FCB-D2F3-4108-890A-13891AF6435E

DocuSign Envelope ID: F1BAEF7C-7F5B-4A06-9C38-94F293026DDA

Form 35R Inspection Response for Form 35 Rev. 3/21

INSPECTION RESPONSE FOR FORM 35

©Copyright 2021 Northwest Multiple Listing Service ALL RIGHTS RESERVED

46

Page 1 of 1 The following is part of the Purchase and Sale Agreement dated March 5, 2023 Tricia Miller Kathy Miller between ("Buver' Buyer Teresa Blaske Robert Blaske and 8510 NE Grove Road Vancouver 98665 concerning (the "Property"). Address BUYER'S RESPONSE OR REQUEST FOR REPAIRS OR MODIFICATION 1. Buyer's inspection of the Property is approved and the inspection contingency is satisfied.* 6 Buyer's inspection of the Property is disapproved and the Agreement is terminated. The Earnest Money shall be refunded to Buyer.* Buyer gives notice of an additional inspection. The inspector's recommendation is attached. The time for Buyer's 10 response to the initial and additional inspection is extended as provided in Paragraph 5 of Form 35.* Buyer requests the following modifications and/or repairs described below or on the attached pages. If Seller 11 agrees to these modifications or repairs, the inspection contingency shall be deemed satisfied.** Note: If Buyer provides any portion of the inspection report to Seller without Seller's prior written consent or as 13 required by Paragraph 5 of Form 35, the inspection contingency shall conclusively be deemed waived. 14 Seller to have licensed/bonded sewer company spot repair section of main sewer line with root penetrations 15 (approximately 2' of pipe 5' deep-bid attached). Seller to have licensed/bonded pest company treat crawl space for 16 active wood boring beetles. (Recommend A&A Pest Managemnt-800-852-3671) Seller to have licensed/bonded 17 roofing company repair active leaks around chimney. Seller to have licensed/bonded chimney/masonry company 18 evaluate and repair chimney firebox, damper and flue to proper working condtion (damaged-cracks-deterioration)-19 Tricia Miller 03-19-2023 20 Buver Date If Buyer requests modifications and/or repairs, this Form 35R and any other addenda or notice pertaining to the 21 modifications and/or repairs and amendment to the Agreement related to or resulting from the request for 22 modifications and/or repairs shall become a part of the Agreement. 23 SELLER'S RESPONSE TO BUYER'S REQUEST FOR REPAIRS OR MODIFICATION. 24 Seller agrees to all of the modifications or repairs in Buyer's request. The inspection contingency is satisfied, the parties 25 agree to proceed to Closing as provided in the Agreement, and Buyer's reply, below, is not necessary.** 26 Seller offers to correct only the following conditions described below or on the attached pages:** 27 Seller to have licensed, bonded pest company to treat crawl space for active wood boring 28 beetles. 29 Seller to have licensed bonded roofing repair for active leaks around the chimney. Seller rejects all proposals by Buyer.* 30 □ Seller rejects all proposals by Buyer, but proposes the following alternative modifications or repairs described 31 below or on the attached pages:** 32 33 DocuSigned by: 34 3/23/2023 3/23/2023 249C04B739814BB. 35 24DC8918AE0448 Date Date 36 III. BUYER'S REPLY TO SELLER'S RESPONSE. Buyer accepts Seller's response and agrees to proceed to Closing as provided in the Agreement.** 37 Buyer rejects Seller's response. Buyer disapproves of the inspection and this Agreement is terminated. The 38 Earnest Money shall be refunded to Buyer.* Buyer rejects Seller's response, but offers the attached alternative proposal for modification or repair. Buyer 40 acknowledges that the inspection contingency will be waived unless Buyer and Seller reach written agreement or 41 Buyer gives notice disapproving the inspection and terminating the Agreement before the deadline in Paragraph 42 6(b) of the inspection contingency (NWMLS Form 35).** 43 44 Buyer Date Buyer Date 45

^{*} This is a notice which requires only one Buyer's or one Seller's signature.

^{**} This is not a notice and requires all Buyer's or Seller's signatures.